



**TROUBLE SHOOTING GUIDE**

PROBLEM	CAUSE	SOLUTION
<b>EXCESSIVE ELECTRODE CONSUMPTION</b>	<ol style="list-style-type: none"> <li>1. Inadequate gas flow.</li> <li>2. Improper size electrode for current required.</li> <li>3. Operating of reverse polarity.</li> <li>4. Electrode contamination.</li> <li>5. Excessive heating inside torch.</li> <li>6. Electrode oxidizing during cooling.</li> <li>7. Shield gas incorrect.</li> </ol>	<ol style="list-style-type: none"> <li>1. Increase gas flow.</li> <li>2. Use larger electrode.</li> <li>3. Use larger electrode or change polarity.</li> <li>4. Remove contaminated portion, then prepare again.</li> <li>5. Replace collet, try wedge collet or reverse collet.</li> <li>6. Increase gas post flow time to 1 sec. per 10 amps.</li> <li>7. Change to proper gas (no oxygen or Co2).</li> </ol>
<b>ERRATIC ARC</b>	<ol style="list-style-type: none"> <li>1. Incorrect voltage (arc too long).</li> <li>2. Current too low for electrode size.</li> <li>3. Electrode contaminated.</li> <li>4. Joint too narrow.</li> <li>5. Contaminated shield gas, dark stains on the electrode or weld bead indicate contamination.</li> <li>6. Base metal is oxidized, dirty or oily.</li> </ol>	<ol style="list-style-type: none"> <li>1. Maintain short arc length.</li> <li>2. Use smaller electrode or increase current.</li> <li>3. Remove contaminated portion, then prepare again.</li> <li>4. Open joint groove.</li> <li>5. The most common cause is moisture or aspirated air in gas stream. Use welding grade gas only. Find the source of the contamination and eliminate it promptly.</li> <li>6. Use appropriate chemical cleaners, wire brush, or abrasives prior to welding.</li> </ol>
<b>INCLUSION OF TUNGSTEN OR OXIDES IN WELD</b>	<ol style="list-style-type: none"> <li>1. Poor scratch starting technique.</li> <li>2. Excessive current for tungsten size used.</li> <li>3. Accidental contact of electrode with puddle.</li> <li>4. Accidental contact of electrode to filler rod.</li> <li>5. Using excessive electrode extension.</li> <li>6. Inadequate shielding or excessive drafts.</li> <li>7. Wrong gas.</li> <li>8. Heavy surface oxides not being removed.</li> </ol>	<ol style="list-style-type: none"> <li>1. Many codes do not allow scratch starts. Use copper strike plate. Use high frequency arc starter.</li> <li>2. Reduce the current or use larger electrode.</li> <li>3. Maintain proper arc length.</li> <li>4. Maintain a distance between electrode and filler metal.</li> <li>5. Reduce the electrode extension to recommended limits.</li> <li>6. Increase gas flow, shield arc from wind, or use gas lens.</li> <li>7. Do not use Ar-O2 or Ar-Co2 GMA (MIG) gases for TIG welding.</li> <li>8. Use ACHF, adjust balance control for maximum cleaning, or wire brush and clean the weld joint prior to welding.</li> </ol>
<b>POROSITY IN WELD DEPOSIT</b>	<ol style="list-style-type: none"> <li>1. Entrapped impurities, hydrogen, air, nitrogen, water vapor.</li> <li>2. Defective gas hose or loose connection.</li> <li>3. Filler material is damp (particularly aluminum).</li> <li>4. Filler material is oily or dusty.</li> <li>5. Alloy impurities in the base metal such as sulphur, phosphorus, lead and zinc.</li> <li>6. Excessive travel speed with rapid freezing of weld trapping gases before they escape.</li> <li>7. Contaminated shield gas.</li> </ol>	<ol style="list-style-type: none"> <li>1. Do not weld on wet material. Remove condensation from line with adequate gas pre-flow time.</li> <li>2. Check hoses and connections for leaks.</li> <li>3. Dry filler metal in oven prior to welding.</li> <li>4. Replace filler metal.</li> <li>5. Change to a different alloy composition which is weldable. These impurities can cause a tendency to crack when hot.</li> <li>6. Lower the travel speed.</li> <li>7. Replace the shielding gas.</li> </ol>
<b>CRACKING IN WELDS</b>	<ol style="list-style-type: none"> <li>1. Hot cracking in heavy section or with metals which are hot shorts.</li> <li>2. Crater cracks due to improperly breaking the arc or terminating the weld at the joint edge.</li> <li>3. Post weld cold cracking, due to excessive joint restraint, rapid cooling, or hydrogen embrittlement.</li> <li>4. Centerline cracks in single pass welds.</li> <li>5. Underbead cracking from brittle microstructure.</li> </ol>	<ol style="list-style-type: none"> <li>1. Preheat, increase weld bead cross-section size, change weld bead contour. Use metal with fewer alloy impurities.</li> <li>2. Reverse direction and weld back into previous weld at edge. Use Ampttrak or foot control to manually down slope current.</li> <li>3. Preheat prior to welding, use pure or non-contaminated gas. Increase the bead size. Prevent craters or notches, Change the weld joint design.</li> <li>4. Increase bead size. Decrease root opening, use preheat, prevent craters.</li> <li>5. Eliminate sources of hydrogen, joint restraint, and use preheat.</li> </ol>
<b>INADEQUATE SHIELDING</b>	<ol style="list-style-type: none"> <li>1. Gas flow blockage or leak in hoses or torch.</li> <li>2. Excessive travel speed exposes molten weld to atmospheric contamination.</li> <li>3. Wind or drafts.</li> <li>4. Excessive electrode stickout.</li> <li>5. Excessive turbulence in gas stream.</li> </ol>	<ol style="list-style-type: none"> <li>1. Locate and eliminate the blockage or leak.</li> <li>2. Use slower travel speed or carefully increase the flow rate to a safe level below creating excessive turbulence. Use a trailing shield cup.</li> <li>3. Set up screens around the weld area.</li> <li>4. Reduce electrode stickout. Use a larger size cup</li> <li>5. Change to gas saver parts or gas lens parts.</li> </ol>
<b>ARC BLOW</b>	<ol style="list-style-type: none"> <li>1. Induced magnetic field from DC weld current.</li> <li>2. Arc is unstable due to magnetic influences.</li> </ol>	<ol style="list-style-type: none"> <li>1. Change to ACHF current. Rearrange the split ground connection.</li> <li>2. Reduce weld current and use arc length as short as possible.</li> </ol>
<b>SHORT PARTS LIFE</b>	<ol style="list-style-type: none"> <li>1. Short water cooled leads life.</li> <li>2. Cup Shattering or cracking in use</li> <li>3. Short collet life.</li> <li>4. Short torch head life.</li> <li>5. Gas hoses ballooning, bursting, or blowing off while hot.</li> </ol>	<ol style="list-style-type: none"> <li>1. Verify coolant flow direction, return flow must be on the power cable lead.</li> <li>2. Change cup size or type, change tungsten position, refer to chart.</li> <li>3. Ordinary style is split and twists or jams. change to wedge style.</li> <li>4. Do not operate beyond rated capacity, use water cooled model, do not bend rigid torches.</li> <li>5. Incorrect flowmeter, TIG flowmeters operate at 35 psi with low flows. MIG flowmeters operate with high flows at 65 psi or more.</li> </ol>

**TOLL FREE ORDER ENTRY**  
**TEL: 1-800-426-0877**  
**FAX: 1-800-327-5038**

**CK WORLDWIDE, INC.**  
**P.O. BOX 1636**  
**AUBURN, WA. 98071**  
**USA**

**CUSTOMER SERVICE**  
**TEL: 1-253-854-5820**  
**FAX: 1-253-939-1746**

**WWW.CKWORLDWIDE.COM**